

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub-District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Yoga - 6.71 x 3.85 m
 Waiting Room - 10.52 x 7.92 m
 Office 3.56 x 3.40
 P. Room - 6.65 x 5.06

Shahrukh KV
 Don Bosco Central School
 Hasabettu Hill, Manjeshwar,
 Kasargod
 class Room 12 Nos. 6.71 x 9.8 -
 Stairs 4 x 5.7 x 3.85
 Store - 6.65 x 5.51
 Toilet - 6.65 x 7.60
 Hall 4.57 x 3.77 m with 5
 m wide passage
 Total plinth area 2222.07 m²
 2023-24

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

}

.....

 Nil

 No


Yes
 Structure is sound for conducting
 classes under normal weather
 conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 31/05/2023 and found to be fit / ~~unfit~~ to conduct classes, for the period 2023-24 for the reasons stated above.

Place: Manjeshwar
 Date: 31/05/23



Shahrukh KV

THE SECRETARY
 (Seal)
THE PAVUR DON BOSCO SOCIETY
DON BOSCO MANJESHWAR
 KERALA - 671 323

Assistant Engineer
Shahrukh KV

The Principal Assistant Engineer
 Don Bosco Central School
 Manjeshwar, Kasargod
 Kerala - 671 323