

TO BE FILLED BY THE INSPECTING OFFICER (ASST. ENGINEER)

- | | | |
|---|---|---|
| 1 | Name of the Officer | AKSHARAK ANIL |
| 2 | Name of the School | DON BOSCO CENTRAL SCHOOL |
| 3 | Location with name of Education District / Sub District | HOSABETTUHILL, MANJESHWARAM
KASARGOD |
| 4 | Classification of Building as specified in column 4 of the application for fitness certificate and size | BASEMENT FLOOR - 651.70 Sqm
1. Computer Room - 7.92 x 6.99 m
2. Store Room - 5.94 x 3.05 m
3. Non Teaching Staff Room - 3.86 x 6.99 m
4. U.K.G Class Room - 1 - 8.33 x 6.99 m
5. U.K.G Class Room - 2 - 8.33 x 6.99 m
6. L.K.G Class Room - 1 - 6.71 x 9.65 m
7. L.K.G Class Room - 2 - 6.71 x 9.65 m
8. Staff Room - 5.00 x 5.62 m |
| 5 | Period for which the certificate is issued | 2026-2027 |
| 6 | Nature of defects, if any | |
| | a) Foundation and basement | Nil |
| | b) Superstructure | Nil |
| | c) Doors and Windows | Nil |
| | d) Wood work wrought and put up | Nil |
| | e) Roof | Nil |
| | f) Flooring | Nil |
| | g) Miscellaneous (Cracks, etc.) | Nil |
| 7 | Any major defects noticed which will render the building unsafe in any manner | No |
| 8 | Whether maintenance works have been done properly | Yes |
| 9 | Whether the structure is sound or not | Yes, Structure is generally sound for conducting class under normal weather condition. |

Note 1 The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.
 2 Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate


Certified that the building was inspected by me on 29/05/2026 and found to be fit for the period 2026-27 for the reasons stated above

Place Manjeshwaram

Signature

Date 29/05/26

Designation

Two copy attested

MANAGER
Don Bosco Central School
Manjeshwar, Kasargod
Kerala - 671 323




The Principal
Don Bosco Central School
Manjeshwar, Kasargod
Kerala - 671 323